

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-008911**Date Inspected:** 03-Sep-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai,China**CWI Name:** Lv Li Qing / Shen Fu You**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Assembly**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Tim McClendon was present during the time noted above for observations relative to the work being performed.

This QA Inspector randomly observed the following work in progress:

OBG Assembly Bay 14

Flux Cored Arc Welding (FCAW) on Floor Beam (FL3) to (FL2-1) of weld joint SEG060 SSD18 PP88 OBG assembly weld numbers 008 and 009 for Segment 9AE. The ZPMC welders identified as 055491 was welding in the 3F position. The ZPMC QC identified as Zhong Guo Hui was monitoring the welding and recording the weld variables. The welding variables recorded by ZPMC QC appeared to comply with the WPS-B-T-2133.

Flux Cored Arc Welding (FCAW) on Floor Beam (FL3) to (FL2-1) of weld joint SEG060 SSD18 PP88 OBG assembly weld number 003 for Segment 9AE. The ZPMC welders identified as 055491 was welding in the 1G position. The ZPMC QC identified as Zhong Guo Hui was monitoring the welding and recording the weld variables. The welding variables recorded by ZPMC QC appeared to comply with the WPS-B-T-2233-B-U2-F.

Flux Cored Arc Welding (FCAW) on Floor Beam (FL3) to (FL2-1) of weld joint SEG060 SSD18A PP88 OBG assembly weld numbers 127 and 128 for Segment 9AE. The ZPMC welders identified as 055564 was welding in the 3F position. The ZPMC QC identified as Zhong Guo Hui was monitoring the welding and recording the weld variables. The welding variables recorded by ZPMC QC appeared to comply with the WPS-B-T-2133.

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

Flux Cored Arc Welding (FCAW) on Floor Beam (FL3) to (FL2-1) of weld joint SEG060 SSD18A PP88 OBG assembly weld number 003 for Segment 9AE. The ZPMC welders identified as 055564 was welding in the 1G position. The ZPMC QC identified as Zhong Guo Hui was monitoring the welding and recording the weld variables. The welding variables recorded by ZPMC QC appeared to comply with the WPS-B-T-2233-B-U2-F.

Shielded Metal Arc Welding (SMAW) on T-Stiffener to Side Panel of weld joint SP 549 - 001 OBG assembly weld numbers 072, 074, 076, 078, 080, 082, 084 for Segment 10AE. The ZPMC welders identified as 200113 was welding in the 4F position. The ZPMC QC identified as Zhong Guo Hui was monitoring the welding and recording the weld variables. The welding variables recorded by ZPMC QC appeared to comply with the WPS-B-T-2114-FCM-1.

Shielded Metal Arc Welding (SMAW) on T-Stiffener to Side Panel of weld joint SP 550 - 001 OBG assembly weld numbers 058, 060, 062, 064, 066, 068, 070 for Segment 10AE. The ZPMC welders identified as 200113 was welding in the 4F position. The ZPMC QC identified as Zhong Guo Hui was monitoring the welding and recording the weld variables. The welding variables recorded by ZPMC QC appeared to comply with the WPS-B-T-2114-FCM-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### Summary of Conversations:

No relevant conversations spoken on this date.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (15000422372), who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	McClendon,Timothy	Quality Assurance Inspector
<b>Reviewed By:</b>	Patterson,Rodney	QA Reviewer

---